



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW2786/1

Work Order Type: Weatherization

Audit Name: 12012NW2786

CLIENT INFORMATION

Client Name:

Address:

Client ID: 12012NW2786

Alt. Client ID: Gibson

AGENCY INFORMATION

Agency: Northwest Tn. Economic Development Council

Agency Phone: (731) 364-3228

Address: 231 South Wilson St.

Fax: (731) 364-5029

Dresden, TN 38225-1312

Email Address:

Agency Contact: Woods, Max

Work Phone: (731) 286-0332

Cell Phone: (731) 676-1414

Email Address: maxrwoods@gmail.com

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 8

Measures

Measure 1 Replace (4) Broken Glass

Components

Inspected

Comment Broken Glass #7 (1)
 #8 (2)
 #9 (1)

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Misc Material	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 8

Measure 2 Infiltration Redctn

Components

Inspected

Comment Foam Kitchen and Bath Sink Plumbing

Pack and Foam Head of Tub

Upgrade/Insulate Attic Access

Use 1/4" O.S.B. And crown to cover seal back bedroom closet (2 x 5) extreme air infiltration

Caulk crown to ceiling, crown to wall through out house

Door #1 Weatherstrip
Threshold
Caulk
Adj. To open and close freely

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Supplies	Infiltration Reduction	Each	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Measure 3 DWH Pipe Insulation

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual				
				Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>					
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>					
Other Detail										
Measure Sub Total:							<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Measure 4 Wall Insulation

Components WL1,WL1 (2),WL1 (3),WL1 (4)

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual				
				Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	Wall Insulation - Cellulose, Blown - 2x4 Filled	SqFt	867.8	<input type="text"/>					
Other Detail										
Measure Sub Total:							<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 8

Measure 5 Floor Ins. R-19

Components F1

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	916	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Measure 6 CO Monitor is Needed

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1	<input type="text"/>				
2	Labor	Labor	Hour	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 5 of 8

Measure 7 Fix Improper Venting (Clothes Dryer)

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1	<input type="text"/>				
2	Labor	Labor	Hour	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Measure 8 Fix Wiring Problems (Attic)

Components

Inspected

Comment Add (4) Junction Box covers in attic, before blowing insulation

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Equipment	Each	1	<input type="text"/>				
2	Labor	Labor	Hour	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 6 of 8

Measure 9 PressureRelief Piping Needed

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1	<input type="text"/>				
2	Labor	Labor	Hour	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Measure 10 Smoke Detector is Needed

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated		Actual			
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1	<input type="text"/>				
2	Labor	Labor	Hour	1	<input type="text"/>				

Other Detail

<input type="text"/>									
<input type="text"/>									

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 7 of 8

**Measure 11 Vapor Barrier Needed
(Basement/Crawlspace)**

Components

Inspected

Comment Vapor Barrier 916 sq.ft.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	Each	1	<input type="text"/>				
2	Labor	Labor	Hour	1	<input type="text"/>				

Other Detail

<input type="text"/>								
<input type="text"/>								

Measure Sub Total:

Sub Total:

Field Notes:

Work Order Grand Total:

Grand Total:

Client Name:

Client ID: 12012NW2786

Alt. Client ID: Gibson

Work Order (Bid Form)

Work Order Name: WO/12012NW2786/1

Report Run On: 5/25/2010

DOE Weatherization Assistant

Version 8.5.0

Page 8 of 8